

**Hamilton Sundstrand
Customer Service**



UTC Aerospace Systems
1 Hamilton Road
Windsor Locks, Connecticut 06096 USA
+1 860 654 6247 Mob +1 860 578 3697
Michael.yezak@utas.utc.com
www.utcaerospacesystems.com

Michael Yezak
Business Development Manager
Aftermarket Customer Services

May 13, 2015

Aircraft Propeller Service, LLC Customer,

Please be advised that Aircraft Propeller Service, LLC has been licensed by **HAMILTON SUNDSTRAND CORPORATION**, a UTC Aerospace Systems Company and **RATIER-FIGEAC SAS**, a UTC Aerospace Systems Company (collectively "UTAS) to perform proprietary repairs (including warranty repairs) on the following propeller models for aircraft located and operating in the regions indicated below:

- 568F
- 247F
- 14SF
- 14RF
- 6/5500
- 24PF

IATA 1 License – Effective Date October 23, 2014

IATA 3 License – Effective Date March 17, 2015

Please contact me directly for any questions related to these licenses. Thank you.

Michael Yezak
Michael.yezak@utas.utc.com